

FIG. 1





FIG. 2





**FIG. 3**

FIG. 4



**FIG. 5**

40



-1	-1	-1	-1	-1
-1	-1	-1	-1	-1
-1	-1	26	-1	-1
-1	-1	-1	-1	-1
-1	-1	-1	-1	-1

FIG. 6A

-1	-1	-1	-1	-1
-1	-1	-1	-1	-1
-1	-1	25	-1	-1
-1	-1	-1	-1	-1
-1	-1	-1	-1	-1

61

FIG. 6B

-1	-1	-1	-1	-1
-1	-1	-1	-1	-1
-1	-1	27	-1	-1
-1	-1	-1	-1	-1
-1	-1	-1	-1	-1

62

FIG. 6C

-1		-1		-1
	-1	-1	-1	
-1	-1	18	-1	-1
	-1	-1	-1	
-1		-1		-1


63

7/28

# FIG. 7

-1	-1	-1
-1	10	-1
-1	-1	-1

FIG. 8





**FIG. 9**




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16B




FIG. 16A






FIG. 17





FIG. 18B


4	1	P	1	4
4	1	1	1	4

FIG. 18A


-8	-4	P	-4	-8
----	----	---	----	----

FIG. 19A



**FIG. 19B**

## FIG. 19C



**FIG. 20A**



**FIG. 20B**



FIG. 20C





**FIG. 20D**



**FIG. 21A**



27/28

# FIG. 21B

FIG. 21B



**FIG. 21C**

